

Internal Wire Harness

• GM 4L60-E • 2003-Later


PART # 350-0061

Installation & Assembly

- Remove old wire harness from valve body.
- Install new Rostra wire harness.
NOTE: Bolt locations may differ from old harness.
- Plug-in connectors as shown in figure below.



GM 4L60-E 2003-Up Valve Body



CAUTION: Care must be taken when reinstalling pan to prevent pinching wires.